



KEYED NOTES:

- 1 1/2" FERROUS METAL E.G. WITH PULL WIRE FOR P.O.S. SYSTEM. CABLES/CABLES SHALL BE FROM EACH P.O.S. TO A HORIZONTAL TO THE OFFICE. CONDUITS SHOULD BE PLACED IN THE SLAB AND STUBBED UP INSIDE A WALL.
- 2 STUB CONDUITS TO ABOVE CEILING INTO TAP CAN. PROVIDE 2" CONDUIT FROM TAP CAN DOWN OFFICE WALL. TERMINATE INTO QUAD JUNCTION BOX. REFER TO 3/2-4 FOR LOCATION OF J-BOX.
- 3 EACH P.O.S. STATION TO HAVE A WALL MTD. DUPLEX I.G. RECEPTACLE AND DOUBLE GANG METALLIC J-BOX WITH SINGLE-GANG PLASTER RING.
- 4 EACH PRINTER TO HAVE A SIMPLEX I.G. RECEPTACLE AND DOUBLE GANG METALLIC J-BOX WITH SINGLE-GANG PLASTER RING.

GENERAL NOTES:

- A ALL COUNTERTOP RECEPTACLES SHALL BE MOUNTED HORIZONTALLY IN BACKSPASH. GENERAL COMMENCEMENT RECEPTACLES SHALL BE MOUNTED VERTICALLY 1" TO CENTER LINE. ALL COVER PLATES ON STAINED OR DARK COLORED WALLS SHALL BE DARK BROWN COLORED. ALL KITCHEN EQUIPMENT COVERPLATES SHALL BE STAINLESS STEEL.
- B PROVIDE #12 ISOLATED GROUND WIRE TO P.O.S./PRINTER OUTLETS.
- C ALL J-BOXES FOR PRINTERS AND P.O.S. ARE TO BE MOUNTED ON THE BACK SIDE OF THE COUNTER WALL. AT 34" AFF UNLESS NOTED OTHERWISE.
- D PROVIDE A 2" GROMMET HOLE IN COUNTER FOR WIRING, TYPICAL EXCEPT AT BAR.

01 FLOOR PLAN - P.O.S.
SCALE 1/4" = 1'-0"

REFER TO SHEET E-2 FOR EQUIPMENT LOCATIONS/DESIGNATIONS AND ELECTRICAL DEVICES RELATED TO P.O.S. SYSTEM

xref: XTBLX50.dwg