



12 DINING 104
1/4"=1'-0"


11 DINING 104
1/4"=1'-0"




05 RECEPTION 102
1/4"=1'-0"




04 RECEPTION 102
1/4"=1'-0"




03 ENTRY ELEVATION
1/4"=1'-0"




02 ENTRY ELEVATION
1/4"=1'-0"




01 ENTRY ELEVATION
1/4"=1'-0"




09 DINING 104
1/4"=1'-0"




08 DINING 104
1/4"=1'-0"




07 DINING 104
1/4"=1'-0"




06 RECEPTION 102
1/4"=1'-0"




13 BAR DINING 107
1/4"=1'-0"




12 DINING 105/106
1/4"=1'-0"




11 CORRIDOR 103
1/4"=1'-0"




10 DINING 104
1/4"=1'-0"




16 DINING 106
1/4"=1'-0"




15 DINING 105
1/4"=1'-0"




14 DINING 105
1/4"=1'-0"




19 DRINK STATION
1/4"=1'-0"



18 DINING 104
1/4"=1'-0"



17 DINING 106
1/4"=1'-0"



28 JAN. 2004
OWNER COMMENTS